Q-Lab Test Services



INSPECTION REPORT

This inspection report contains only findings and results arrived at after employing the specific test procedures listed in the Test Confirmation. It does not constitute a recommendation for, endorsement of, or certification of the product or material tested. Q-Lab Test Services makes no warranty, expressed or implied, except that the test has been performed, and a report prepared, based upon the specimen or specimens furnished by the client. Extrapolation of data from the specimen or specimens relating to the batch or lot from which it was obtained may not correlate and should be interpreted accordingly with extreme caution. Measurement uncertainty is not considered when stating conformity to specified performance requirements. We assume no responsibility for variations in quality, composition, appearance, performance, or other feature of similar subject matter produced by other persons or under conditions over which we have no control. This report shall not be reproduced except in full without the written approval of Q-Lab Test Services.

CLIENT: Lightweight Tiles, Ltd.

ADDRESS: Unit 138, Lydney Industrial Estate, Harbour Road, Lydney

Gloucestershire GL15 4EJ

UNITED KINGDOM

ATTN: Mr. Bruce Bennett

YOUR REFERENCE:

CONTENTS: Cover Sheet: Page 1

Report: Page 2

Marie Jones Marie Jones

Ana Ferrera

Ana Ferrera Inspected By:

Approved By:

TEST NO: LTL-1

REPORT NO:

DATE: 5 January 2023

DATE EXPOSED: **5 January 2021**

DURATION: 24 Months

TYPE: Direct Inland, 5° South-Florida

SPECIMENS: 4 Coated roof specimens

RADIATION LOG:TOTAL = 12,954.55 MJ/m²

> TUVR = 716.85MJ/m²

NOTES: Please refer to the legend located on our website at www.myweathertest.com for an explanation of the ratings

used in this report.

Any sign of brittleness will be noted in the Comments section.

Note 1. Specimen exhibits moderate yellowing along

the center of the specimen.

Note 2. Specimen exhibits moderate loss of gloss.





TEST NO: LTL-1 REPORT NO: 4 DATE: 5 January 2023

Specimen ID	Gen.						Visual	Dirt	Mildew	Chalk	Crack	Comments
	Арр.						Color	l				
X1 Brown Coated Tile	7						7 F	10	10	10	10	
X1 Opaque Tile	4						9 D	7	4	8	10	Previously fading, see Note 1.
X1 UV Black Tile	6						6 F	8	10	9	10	See Note 1 and 2.
X1 UV Red Tile	7						7 F	9	10	10	10	See Note 2.